


Work on the buttresses has begun. Stone mason was here this fall and stabilized the worst sections and will return in May/April to finish work on the buttresses and the front stairwell. The buttresses and front stairs have deteriorated significantly. This will be a major project with a substantial cost which will be approximately \$35,000.00 to \$40,000.00.



In places, one can actually put their whole arm into the gaps and sections are falling off.






Buttress 3 right side of church. Rocks fallen out and large section ready to fall out



This whole section is loose and ready to fall out

Buttress 1 right side of church looking from front of church







Loose section

Missing rock section

Loose rock

Missing rocks

Loose rock

Right side of front entrance





Left side of front stairwell. Rocks are beginning to separate from the cement steps. Each year it gets worse as water freezes in the crack.



Right side of front stairwell. Rock wall is beginning to separate from the concrete steps due to water freezing in winter.

Also notice all the loose rocks which have fallen out of the rock sidewalls





**This section is completely loose and the bottom of the gate post is rusted off.**



**These rocks are loose and ready to fall out**